CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of ROCKLIN

Document Number _____

Brief Legal Description A PORTION OF SEC. 19, T.11N., R.7E., M.D.B.&M.



CORNER TYPE

Government Corner ☐ Control ☐

Meander ☐ Property ☒ PER 9 RS 103

Rancho ☐ Other ☐

Date of Survey 1-26-96

COORDINATES *(Optional)*

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

LOCATED ORIGINAL MONUMENTS (9 RS 103 ROS №1026) PRIOR TO CONSTRUCTION OF PACIFIC STREET IMPROVEMENTS. RESET AT FOUND LOCATION AFTER CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: Fd. 3/4" I.P. w/PLASTIC PLUG STAMPED LS3333 — SET 3/4" REBAR w/TAG LS6789

BOOK 5 CORNER RECORDS PAGE 28

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1-26 1996.

Signed Robert Halstead L.S. or R.C.E. Number LS6789

LICENSED LAND SURVEYOR ★ ROBERT HALSTEAD EXP. 9-30-96 SEAL No. 6789 ★ STATE OF CALIFORNIA

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 31 1996 and examined

and filed FEB 20 1996.

Signed John Rietjens Title DEPUTY COUNTY SURVEYOR

LICENSED LAND SURVEYOR ★ JOHN H. RIETJENS SEAL ★ STATE OF CALIFORNIA L.S. 4323 6/30/96

County Surveyor's Comment _____

NOT TO SCALE

NORTH

CENTER OF SEC. 19
---- Fd. GRANITE MON. W/CHIS. CROSS PER R-1.

PACIFIC STREET

℄

901.50'M. (901.28'R-1)

Fd. 3/4" I.P. DISTURBED BY CONSTRUCTION
REPLACED W/ 3/4" REBAR
W/ TAG LS 6789 @ REC.
BRG. & DIST.

SCOPESI
1925 O.R. 477

N88°51'00"E R-1 & M.

437.01'R-1 & M.

Fd. 3/4" I.P. W/ PLASTIC PLUG
STAMPED LS3333 PER R-1.

LEGEND:

(R-1) = RECORD PER ROS BK 9 PG 103

M. = FIELD MEASURED

● = FOUND MONUMENT AS NOTED

⌀ = SET 3/4" REBAR W/ TAG LS 6789