CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description SOUTHEAST COR. PCL. C AS SHOWN ON 22PM123. NE¼ SEC 26, T11N-R7E, M.D.M.



CORNER TYPE

Government Corner	☐	Control	☐
Meander	☐	Property	☒
Rancho	☐	Other	☐

Date of Survey _____

COORDINATES *(Optional)*

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

USED FOUND CORNERS OF PARCEL C TO SET THE SOUTHEAST CORNER OF THIS PARCEL AS SHOWN ON 22 PM 123. THE ORIGINAL CORNER WAS DESTROYED DURING TRENCHING FOR UTILITIES.

A description of the physical condition of the monument as found and as set or reset: SET AN IRON PIPE, 1" OUTSIDE DIAMETER, WITH 1 1/4" CAP STAMPED: "LS 5949 - 1994"

BOOK 4 CORNER RECORDS PAGE 81

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on NOVEMBER 14, 19 94.

Signed Don P. Meesman (L.S.) or R.C.E. Number 5949

LICENSED LAND SURVEYOR DON PERRY MESSMAN 12-31-96 Exp. SEAL LS5949 STATE OF CALIFORNIA

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOV 15 19 94 and examined and filed 12/8 19 94.

Signed John Rietjens Title DEPUTY COUNTY SURVEYOR

LICENSED LAND SURVEYOR JOHN H. RIETJENS SEAL 6/30/96 L.S. 4323 STATE OF CALIFORNIA

County Surveyor's Comment _____

FD. 1 1/2" IRON PIPE
WITH TAG LS 3639
PER 22 PM 123

N 0°08'42" W
200.00

PCL C
22 PM 123

SET 1" OUTSIDE DIA
IRON PIPE WITH 1 1/4" CAP
STAMPED "LS 5949 1994"
IN POSITION OF DESTROYED COR.

S 89°51'18" W
310.16

N 87°43'22" E
420.00

FD 1" IRON PIPE
NO TAG (LS 3639)
PER 22 PM 123

FD 1 1/4" IRON PIPE
WITH PLUG
NO TAG (LS 3639)
PER 6 PM 50

PCL A
6 PM 106

N 0°15'54" W
200.00

FD 3" OUTSIDE DIA
MUSHROOMED IRON PIPE
WITH PLUG & TAG LS 3639
PER 6 PM 107

1"=100' ±