CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of ROCKLIN

Document Number

Brief Legal Description A PORTION OF SEC. 19, T. 11N., R. 7E., M. D. B. & M.



CORNER TYPE

Government Corner	☐	Control	☐	
Meander	☐	Property	☒	9 RS 103
Rancho	☐	Other	☐	

Date of Survey 1-18-96

COORDINATES *(Optional)*

N.

E.

Zone Datum

Elev.

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

LOCATED ORIGINAL MONUMENTS (ROS 9 RS 103 No. 1026) PRIOR TO CONSTRUCTION OF PACIFIC STREET IMPROVEMENTS. RESET AT FOUND LOCATION AFTER CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: Fd. 3/4" I.P. w/ PLASTIC PLUG STAMPED LS 3333 - SET 3/4" REBAR w/ TAG LS 6789. Fd. NAIL HOLE AND PAINT IN CONCRETE SLAB AT ROCK BIN - RESET NAIL AND TAG LS 6789.

BOOK 5 CORNER RECORDS PAGE 31

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1-29 1996.

Signed Robert Halstead L.S. or R.C.E. Number LS6789

LICENSED LAND SURVEYOR ROBERT HALSTEAD EXP. 9-30-96 SEAL No. 6789 STATE OF CALIFORNIA

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 31 1996 and examined

and filed FEB 20 1996.

Signed John Rietjens Title DEPUTY COUNTY SURVEYOR

LICENSED LAND SURVEYOR JOHN H. RIETJENS SEAL L. S. 4323 STATE OF CALIFORNIA 2/20/96

County Surveyor's Comment

NOT TO SCALE

PACIFIC STREET

N28°31'08"E

℄

25'

KEST1
1500 O.R. 181

Fd. 3/4" I.P. W/PLASTIC CAP STAMPED LS 3333. RESET 3/4" REBAR W/TAG LS 6789.

N28°57'14"W R.M.
172.07' M.
(172.00' R.)

CONCRETE SLAB ROCK BIN.

Fd. NAIL HOLE AND PAINT IN CONCRETE SLAB. RESET NAIL AND TAG LS 6789.

SCOPES1
1925 O.R. 477

LEGEND:

R = RECORD PER ROS BK 9 PG 103

M = FIELD MEASURED

● = FOUND MONUMENT AS NOTED