CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of ROCKLIN

Document Number

Brief Legal Description A PORTION OF SEC. 19, T.11N., R.7E., M.D.B.&M.



CORNER TYPE

Government Corner ☐ Control ☐

Meander ☐ Property ☒ 9 RS 103

Rancho ☐ Other ☐

Date of Survey 1-18-96

COORDINATES (Optional)

N.

E.

Zone Datum

Elev.

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

LOCATED ORIGINAL MONUMENTS (9 RS 103 ROS Nº 1026) PRIOR TO CONSTRUCTION OF PACIFIC STREET IMPROVEMENTS. RESET AT FOUND LOCATION AFTER CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset: Fd. 3/4" I.P. W/PLASTIC PLUG STAMPED LS 3333 - SET 3/4" REBAR W/TAG LS 6789

BOOK 5 CORNER RECORDS PAGE 30

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 1-26 1996.

Signed [signature] L.S. or R.C.E. Number LS 6789

LICENSED LAND SURVEYOR ROBERT HALSTEAD EXP. 9-30-96 No. 6789 STATE OF CALIFORNIA SEAL

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN 31 1996 and examined

and filed FEB 20, 1996 19 ____.

Signed [signature] Title DEPUTY COUNTY SURVEYOR

LICENSED LAND SURVEYOR JOHN H. RIETJENS 6/30/96 L. S. 4323 STATE OF CALIFORNIA SEAL

County Surveyor's Comment


CENTER OF SEC. 19
Fd. GRANITE MON. w/CHIS. CROSS
PER R-1.
NOT TO SCALE
177.51' M.
(177.27' R-1)
396.62' M.
(396.00' R-1)
PACIFIC STREET
Fd. 3/4" I.P. LS 3333
RESET 3/4" REBAR
WITH TAG LS 6789.
219.13' M.
(218.73' R-1)
N63°52'10"W R-1 & M.
LEGEND:
(R-1) = RECORD PER 9 RS 103
M. = FIELD MEASURED
● = FOUND MONUMENT AS NOTED
ø = SET 3/4" REBAR w/TAG LS 6789
Fd. 3/4" I.P. w/PLASTIC PLUG
STAMPED LS 3333 IN ROCK MOUND
@ FENCE COR. PER R-1.