CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description W½ corner Lot 523, Dollar Point Unit No 7, I Maps 41



SEC 33
T 16 N
R 17 E
MDM

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey 23 Oct 2000

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☒

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

found ½" dia iron pin commonly found as original lot corners in this unit, (called as ¾" ironpin by I Maps 41) pin bent over at top by construction equipment during paving operations on State Hwy 28. Check Chained between this corner and 3 corners to SW, NE & SE returning record distances

A description of the physical condition of the monument as found and as set or reset:

spun bent monument & found clean, straight, vertical hole in Decomposed granitic soil. Reset a ¾" rebar in original hole w/ aluminum cap stamped as shown on reverse. Set at request of CalTrans Resident Engineer

E.A.

BOOK 6 CORNER RECORDS PAGE 76

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 24 Oct 2000 19 ____.

Signed _____ L.S. or R.C.E. Number 6230

LICENSED LAND SURVEYOR MARC A. WALCZUK STATE OF CALIFORNIA SEAL No. 6230 Exp. 31 Mar 2002

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed Nov 16, 2000 19 ____.

Signed John Rietjens Title County Surveyor

LICENSED LAND SURVEYOR JOHN H. RIETJENS SEAL 6-30-2004 L.S. 4323 STATE OF CALIFORNIA

County Surveyor's Comment _____



BOOK 6 CORNER RECORDS PAGE 76