CORNER RECORD

Document Number _____

City of _____ County of Placer, California

Brief Legal Description Parcel "B" 6 PM 33 NW1/4 Sec. 34, T13N-R7E, M.D.M.



Sec 34, T13N-R7E

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☐
Rancho ☐ Other ☐

Date of Survey 16 February 2006

COORDINATES(Optional)

N.
E.
Zone _____ NAD27 ☐ NAD83
NAD83 Epoch
Elevation
Vert. Datum: NGVD29 ☐ NAV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
SW corner RR spike LS3639 2" below surface and 1-1/2 pipe LS3639 tag found set at angle point on East line

A description of the physical condition of the monument as found and as set or reset: Set reference points on South portion of West line - 5/8 bars with LS3639 cap

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 24 February, 2006

Signed Ralph Miller P.L.S. or R.C.E. Number LS 3639

LICENSED LAND SURVEYOR RALPH MILLER L.S. 3639 Exp. 06-30-2008 STATE OF CALIFORNIA

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined and filed NOVEMBER 14 2007

Signed Chas. B. Grant P.L.S. or R.C.E. Number LS 6158

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment

LICENSED LAND SURVEYOR CHARLES B. GRANT Exp. 3-31-08 No. 6158 STATE OF CALIFORNIA

BOOK 11 CORNER RECORDS PAGE 6


S 88°35'00"W 285.80'
S 0°29'00"W 1472.28' O.A.
N 0°51'00"E 1062.18'
PARCEL "B"
6 PM 33
N
Found 1 1/2 Pipe
LS 3639 tag
Set Nail @ gate
PARCEL "B"
6 PM 33
NW1/4 SEC. 34
T13N-R7E,
M.D.M.
N00°29'00"E 396.71'
364.72'
297.93'
172.98'
Set 5/8 bar with
LS 3639 cap as
refernce points
to found RR spike
N 7°04'30"E 454.86'
29.96'
Found RR Spike
S 81°25'00"E 228.92'