COUNTY OF Placer T. 13N R.	12E M.D.M. MERIDIAN CALIFORNIA
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CORNER IDENTIFICATION — DATE OF VISIT	
23 0-24-	
CORNER — LEFT AS FOUND   FOUND AND TAGGED   REESTABLISHED OBLITERATED CORNER   REBUILT	
Rock mound.	
50" Ponderosa Pine original BT w/part 17.6 feet (GLO 28" S 84 W 16.5 feet).	tly overgrown blaze chopped out N 89 W
41" Cedar original BT "1/4" clearly v (GLO 22" N 4.5 E 48.2 feet).	visible in opened blaze N 07 E 48.9 feet
NOTE: The GLO calls for these trees	1 mile west of here!
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED  Set 1 1/2" CIP in rebuilt rock mound	stamped (5 32 79)
	TISNIKIZE
Blazed and scribed new BT 13" Douglas	; Fir N 05.5 E ZZ.5 reet.
This corner is 4.5 chains south of Ne	evada Point Road.
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECON	
STATIONS USED: NGS (USC & GS) _ STATE _ COUNTY _	ND THIRD THIRD STATION STATION
ZONE ELEVATION NORTHINGS (Y) _	EASTINGS (X)
	(Fold)
SKETCH: (Include reference tie or witness points, remarks and topo	of area)
This is a relatively flat area with n	no distinguishing terrain features nearby
Corner was found by Larry Hyder, Reg. and remonumentation by Homer Banks, J	Forester No. 1454 Field confirmation r LS 3279.
All BTs have properly marked BT tags.	
SURVEYOR'S CERTIFICATE	
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED Feb. 5 1976
ONAUG 2 1 1675	AND EXAMINED AND FILED March 5 1976  BY: Sted bilinder
STATE OF PARTY.	TITLE: Deputy County Surveyor
L.S. or R.C.E. No.:	DOCUMENT No.
SEATON	STATEMENT ON BACK OF SHEET  YES NO NO
一意 No. 3279 元。 → No. 3279 元。	

P2