


CORNER RECORD

Document Number 20160024

City of UNINCORPORATED AREA County of PLACER, California

Brief Legal Description LOTS 56-59 BLOCK XY, BROCKWAY VISTA SUBDIVISION
BOOK "D" OF MAPS PAGE 16 P.C.D.R.



CORNER TYPE

SEC.19 Government Corner Control
 T.16N. Meander Property
 R.18E. Rancho Other
 M.D.M. Date of Survey 4/25/16

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert.Datum: NGVD29 NAVD88
 Meas. Units Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- = FOUND 1/2" IRON PIN PER 21/SUR/15 P.C.D.R., TAG MISSING
- = FOUND 5/8" REBAR, NO TAG PER 34/PM/157 P.C.D.R.
- = FOUND 3/4" IRON PIPE, NO TAG PER 34/PM/157 P.C.D.R.
- = FOUND 1/2" IRON PIPE, CONCRETE FILLED W/ NAIL
- ▲ = FOUND 3/4" IRON PIPE NO TAG, SET IN CONCRETE 0.5' BELOW GROUND

A description of the physical condition of the monument as found and as set or reset:

○ = SET BATHEY MONUMENT (T-BAR) W/ NAIL & TAG STAMPED P.L.S. 8628

JN: 16020

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyor's Act on MAY 13, 2016

Signed [Signature] P.L.S. or R.C.E. No. 8628
Lic. Exp. 12/31/17



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed February 8, 2017

Signed [Signature] P.L.S. or R.C.E. No. 6584

Title County Surveyor

County Surveyor's Comment _____



BOOK 19 OF CORNER RECORDS, PAGE 54

