


CORNER RECORD

COUNTY OF PLACER T. 10N R. 7E MD BEM MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT 25 JANUARY 1989



N 1/4 CORNER SECTION 16, ALSO THE N.W. CORNER
"TREELAKE UNIT NO. 2-A"
P MAPS 52

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1 1/4" I.P. WITH 2" BRASS CAP PER 6 SUR. 100 O.R.P.C.
33 RS11 O.R.S.C. STAMPED

1971
1/4 59
516
L.S. 3636

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 2" BRASS CAP ON TOP OF 2" I.P. IN
MONUMENT WELL STAMPED AS SHOWN:

1989
1/4 59
516
L.S. 4715

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Book 2, CORNER RECORDS, PAGE 99

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEBRUARY 10 1989

SIGNED: William F. McKinney

L.S. or R.C.E. No.: LS 4715

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 2/14 1989

AND EXAMINED AND FILED 10/24 1991

BY: Barbara McDaniel

TITLE: ASSOCIATE SURVEYOR

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO



NOTE:

ORIGINAL CORNER SET BY L.S. 3636 WAS
DESTROYED DURING CONSTRUCTION OF SUBDIVISION.
TREE LAKE UNIT 2-A, FILED P/MAPS/52, P.C.R.

Root N. corner reference record

