BOOK 24 of CORNER RECORDS PAGE 30

CORNER RECORD

Agency Index BL 2

Document Number 20210062 Placer California City of County of RECORD OF SURVEY #2241, BOOK 16 OF SURVEYS, PAGE 75 Brief Legal Description **CORNER TYPE COORDINATES (Optional)** E. Government Corner Control Elevation **Property** Units U.S. Survey Foot Meander Metric Other Rancho **Horizontal Datum** Zone **Epoch Date** Date of Survey AUGUST 8, 2018 Vertical Datum Complies with Public Resources Code §§8891-8819 Complies with Public Resources Code §§8890-8902 8773 PLS Act Ref.: 8765(d) X 8771(c) Other: Left as found Established Pre-Construction Rebuilt Corner/ **Monument:** Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): FOUND 3/4" IRON PIPE WITH CAP, NUMBER ILLEGIBLE, BELIEVED TO BE PER RECORD OF SURVEY #2241, RECORDED IN BOOK 16 OF SURVEYS, PAGE 75, P.C.R. AT THE NORTH RIGHT-OF-WAY LINE OF LIVOTI AVENUE, AS NOTED AND DEPICTED ON PAGE 2. FOUND (2) 3/4" IRON PIPES NO TAG USED AS REFERENCE POINTS AS NOTED AND DEPICTED ON PAGE 2. SET MAG NAIL REFERENCE POINT AS NOTED AND DEPICTED ON PAGE 2. **SURVEYOR'S STATEMENT** This Corner Record was prepared by me or under my direction in conformance with **AUGUST 5, 2021** the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. RCE33407 Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received and examined and filed Signed

County Surveyor's Comment

Title