


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description S 1/4, Section 32, T17N, R 17E, M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 5/20/01

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Replaced existing stone (see sketch on back)


A description of the physical condition of the monument as found and as set or reset:

(see sketch on back)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on June 18 2001.

Signed [Signature] P.L.S. or R.C.E. No. 3422



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 25, 2001

and examined and filed Jan 10, 2002

Signed [Signature] P.L.S. or R.C.E. No. 4323

Title County Surveyor

County Surveyor's Comment _____



BOOK 7 CORNER RECORDS PAGE 15



CORNER RECORD

SOUTH 1/4 SECTION CORNER OF S32, T17N, R17E, M.D.B. & M.

COUNTY OF PLACER

CALIFORNIA
JUNE 18, 2001

⊗ FOUND 15"x9"x6" STONE, SET FIRMLY IN GROUND, MARKED 1/4 ON WESTERLY FACE. (SEE PHOTO BELOW - 1/4 IS IN CENTER OF DRAWN CIRCLE)
REPLACED WITH 2.5" BERNTSEN A1BR30 ALUMINUM BREAK-OFF MONUMENT, WITH 3.25" ALUMINUM CAP, MARKED AS SHOWN BELOW, IN 4' DIAMETER ROCK AND EARTH MOUND.
PLACED STONE FACE DOWN ON WESTERLY SIDE OF NEW MONUMENT. NEW BEARING TREES SCRIBED AND MARKED WITH METAL FOREST SERVICE BEARING TREE POSTERS AS SHOWN ON RIGHT. ONE ALUMINUM NAIL SET IN SIDE OF EACH TREE AT CENTERLINE.



CORNER HISTORY:

1865 - "SET STONE 15x9x6, FOR 1/4 SEC. COR. FROM WHICH A FIR, 35 IN. DIA. BEARS N27 1/4W, 33 LKS. DIST. YELLOW PINE, 55 IN. ' ' S11 1/2E, 86 ' ' " (PER ORIGINAL GLO SURVEY PERFORMED BY E. DYER)
-FOUND EVIDENCE OF ROTTING STUMPS AT RECORD BEARING TREE LOCATIONS.

1971 - "1/4 CORNER NOT FOUND" (PER NORTHSTAR UNIT 1A SUBDIVISION MAP, J/MAPS/38, O.R.P.C.)
-FROM WHAT I COULD DETERMINE, NO ONE HAS RECORDED SEEING THIS MONUMENT SINCE DYER SET IT IN 1865.

BOOK 7 CORNER RECORDS PAGE 15

J/N-2000.00B