

CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description Reset NE corner of 6 RS 18

	<u>SEC. 20</u> <u>T. 12 N.</u> <u>R. 7 E.</u>	CORNER TYPE		COORDINATES (Optional)	
	Government Corner <input type="checkbox"/> Meander <input type="checkbox"/> Rancho <input type="checkbox"/> Date of Survey _____	Control <input type="checkbox"/> Property <input checked="" type="checkbox"/> Other <input type="checkbox"/>	N. _____ E. _____ Zone _____ Datum _____ Elev. _____		


Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Found 3/4" rebar at NE corner of 6 RS 18 as shown on 16 RS 28 in February of 2000. May 11, 2001 property owner requested to reset corner monument because it had been destroyed by new fence construction.

A description of the physical condition of the monument as found and as set or reset: Reset corner with nail and tag RCE 28217 at position of original corner. Now set on top of wood peeler core post.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 14 19 2001
Signed [Signature] or R.C.E. Number 28217



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JUNE 18, 2001 and examined and filed MARCH 12, 2002
Signed [Signature] Title COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 7 CORNER RECORDS PAGE 22

