


CORNER RECORD

Document Number _____

City of _____ County of PLACER, California

Brief Legal Description LOTS 23 AND 24 MARTIS WOODS ESTATES
BOOK N° OF MAPS PAGE 27 P.C.R.



SEC. 22
T. 17N.
R. 16E.
M. D. M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 7-28-00

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- ⊙ = FOUND 2" CAPPED IRON PIPE, NO TAG (SEE DIAGRAM ON REVERSE)
- = FOUND 3/4" CAPPED IRON PIPE STAMPED L.S. 4165
- ⊙ = FOUND 3/4" IRON PIPE W/PLASTIC PLUG ~~R.C.E.~~ R.C.E. 20257

A description of the physical condition of the monument as found and as set or reset:

- ⊙ = SET 3/4" IRON PIPE W/PLASTIC PLUG L.S. 5549
- ⊙ = SET CHISEL CROSS ON BOULDER
- ⊙ = SET CHISEL CROSS ON WATER BOX

VN, 00205

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 31 2000

Signed Charles R. Sage P.L.S or R.C.E. No. L.S. 5549

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 14, 2001

and examined and filed MARCH 12, 2002

Signed John H. Rietjens P.L.S or R.C.E. No. 4323


Title COUNTY SURVEYOR

County Surveyor's Comment _____




BOOK 1 CORNER RECORDS PAGE 23

DETAIL N.T.S.



FOUND 2" CAPPED IRON PIPE, NO TAG,
 0.6' SOUTH & 0.5' EAST OF TIE-UP COR. POSITION
 NO EVIDENCE OF 5/8" REBAR L.S. 3422, PER 26/PM/153
 WAS FOUND. NOTHING SET
 (SEE DETAIL)

PARCEL 2
 P.M. BK. 26
 PG. 153



SCALE 1" = 100'

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE
 RECORD PER "N"/MAPS/27. NO MATERIAL
 DISCREPANCIES WITH RECORD INFORMATION
 WERE FOUND

BOOK 7 CORNER RECORDS PAGE 23