

CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number 20070001

Brief Legal Description Lot 22 Emigrant Gap Acres I/Maps/4

	NW 1/4	CORNER TYPE		COORDINATES (Optional)	
	SEC 1	Government Corner <input type="checkbox"/>	Control <input type="checkbox"/>	N. _____	
	T 16N	Meander <input type="checkbox"/>	Property <input checked="" type="checkbox"/>	E. _____	
	R 11E	Rancho <input type="checkbox"/>	Other <input type="checkbox"/>	Zone _____ Datum _____	
		Date of Survey _____		Elev. _____	


Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Found three corners of Lot, set missing corner at Record position

A description of the physical condition of the monument as found and as set or reset: 3/4" Rebar with plastic cap MKD LS 3062


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 1, 2007.
Signed Emerson L. Smith L.S. or R.C.E. Number LS 3062



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT 26 2007 and examined and filed JANUARY 15 2008.
Signed Charles B. Grant Title DEPUTY COUNTY SURVEYOR
LS 6158



County Surveyor's Comment _____

BOOK 11 CORNER RECORDS PAGE 39

LEGEND
 ● FND 1/2" REBAR SET IN CONCRETE NOT PRACTICAL TO TAG
 ● FND 1/2" PIPE SET IN CONCRETE AFFIXED TAG LS 3062
 ○ SET 3/4" REBAR WITH PLASTIC CAP W.K. DLS 3062

A PORTION OF THE N.W. 1/4 OF SECTION 1, T10N. R11E. M.D.M. BEING LOT 22 OF EMIGRANT GAP ACRES BK. I Pg. 4

