


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description RECORD of SURVEY No. 1131 10-SURVEYS - 27



SEC. 23
T. 13 N.
R. 5 E.
M.D.M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey NOV 03

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND 2" BRASS CAP IN MONUMENT BOX AT THE INTERSECTION OF
DOWD ROAD AND DALBY ROAD STAMPED FOR THE E. 1/4 CORNER of
Sec. 23, T. 13 N., R. 5 E., LS 3480, 1985, PER RECORD OF SURVEY
No. 1131 at BOOK 10 of SURVEYS, PAGE 27 O.R.P.C., ESTABLISHED
REFERENCE POINTS FROM FOUND MONUMENT PRIOR TO ROAD CONSTRUCTION.

A description of the physical condition of the monument as found and as set or reset:


FROM REFERENCE POINTS SET 2 1/2" BRASS CAP IN MONUMENT BOX
STAMPED FOR 1/4 Cor. Sec. 23:24, T. 13 N., R. 5 E., LS 7887, 2004.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on FEBRUARY 2 2004.

Signed [Signature] L.S. or R.C.E. Number LS 7887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February, 6 2004 and examined

and filed MARCH 1 2004.

Signed Charles B. Grant Title DEPUTY COUNTY SURVEYOR
LS 6158



County Surveyor's Comment _____

BOOK _____ CORNER RECORDS PAGE _____

10-SURV-27



DOWD RD

DALBY RD

**FOUND 2" BRASS CAP IN
MONUMENT BOX, STAMPED FOR
1/4 Cor. Sec. 23*24, T.13 N., R.5 E.,
LS 3480, 1985.**

**SET 2-1/2" BRASS CAP IN
MONUMENT BOX STAMPED FOR
1/4 Cor. Sec. 23*24, T.13 N., R.5 E.,
LS 7887, 2004.**