


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description TREELAKE SUBDIVISION UNIT No. 2-A P-MAPS-52



SEC. 16
TION
RTE
M.D.M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey Mar 19, 2003

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND 3/4" IRON PIPE IN TRAVELED WAY OF TREELAKE Rd. Per
BOOK 'P' of MAPS Page 52, TREELAKE SUBDIVISION UNIT No. 2-A. FROM
FOUND MONUMENTS ESTABLISHED REFERENCE POINTS PRIOR TO ASPHALT
OVERLAY

A description of the physical condition of the monument as found and as set or reset:


FROM REFERENCE POINTS SET P.I.K NAIL WITH 1/4" BRASS WASHER
STAMPED "PLA CO SURVEY" CENTERED OVER FOUND MONUMENTS.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on April 21 20 03.

Signed [Signature] L.S. or R.C.E. Number LS 7887




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received April 25 20 03 and examined

and filed JUNE 24 2003.

Signed Charles B. Grant LS 6158 Title DEPUTY COUNTY



County Surveyor's Comment _____

BOOK 00 CORNER RECORDS PAGE 31

