

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of \_\_\_\_\_ Document Number \_\_\_\_\_

Brief Legal Description Parcels 1 and 2, 27 P.M. 144, P.M No. P-75434

CORNER TYPE

COORDINATES (Optional)



TIIN  
RTE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey June 03, 2003

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:  
Corner replaced between found 1/2" rebar with plastic cap stamped "LS 6376" at NW corner of Parcel 2 and found Railroad Spike at SW corner of Parcel 1 as shown on 27 P.M. 144.

A description of the physical condition of the monument as found and as set or reset: No corner found at NW corner Parcel 1 / SW cor Parcel 2, reestablished with a set Railroad Spike stamped "L.S. 4751".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyor's Act on June 3, 20 03.


Signed [Signature] L.S. or R.C.E. Number L.S. 4751

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 6 20 03 and examined


and filed JUNE 24 2003.

Signed Charles B Grant LS 6158 Title DEPUTY COUNTY SURVEYOR




6.18-03

County Surveyor's Comment \_\_\_\_\_



BOOK 8 CORNER RECORDS PAGE 37



HELMS LANE

N 0° 17' 49" E 952.75'

432.46' 525.29'

FD 1/2" REBAR W/ PLASTIC  
CAP STAMPED "LS 6376"

PARCEL 2  
27 PM 144

SET RR SPIKE  
STAMPED "LS 4751"

PARCEL 1  
27 PM 144

FD RR SPIKE