


CORNER RECORD

Document Number 20070018

City of _____

County of Placer, California

Brief Legal Description Por. Southeast Quarter Section 16, T12N-R7E, M.D.M.

CORNER TYPE		COORDINATES(Optional)	
	<u>Sec. 16</u>	Government Corner <input type="checkbox"/>	Control <input type="checkbox"/>
	<u>T12N</u>	Meander <input type="checkbox"/>	Property <input checked="" type="checkbox"/>
	<u>R7E</u>	Rancho <input type="checkbox"/>	Other <input type="checkbox"/>
	Date of Survey <u>3 July 2007</u>		
		N. _____	
		E. _____	
		Zone _____ NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/>	
		NAD83 Epoch _____	
		Elevation _____	
		Vert. Datum: NGVD29 <input type="checkbox"/> NAV88 <input type="checkbox"/>	
		Meas. Units: Metric <input type="checkbox"/> Imperial <input type="checkbox"/>	

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4 rebar LS 2515 Southerly on East line and 1/2 pipes with no markings at East angle point, Northeast corner and Northwest corner.

A description of the physical condition of the monument as found and as set or reset: East angle point and Northeast corner in proper shape. Placed LS 3639 identifier on each. Northwest corner buried and mangle. No tag placed.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on 3 July 2007

Signed Ralph Miller P.L.S. or R.C.E. Number LS 3639



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____ and examined _____

and filed MARCH 28 2008

Signed Charles B. Grant P.L.S. or R.C.E. Number 6158
 LICENSE EXPIRES 3-31-10

Title DEPUTY COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 12 CORNER RECORDS PAGE 7

Found mangled 1/2 pipe buried 3". Unable to tag. Referred to as 3/4 bar LS 2846 per 7RS82

S 83°50'00"W
302.26'

Found 1/2 pipe placed LS 3639 cap

N 10°06'40"E
101.96'

N 11°47'15"E
155.01'

CARLILE
1355/114

N 6°10'00"W
544.91'

N 8°27'30"W
163.16'



n.t.s.

Centerline 50' Road
and Utility Easement
(1816/224)

N 40°13'30"W
145.97'

N 55°47'00"W
92.78'

Found flared 1/2 pipe placed LS 3639 tag (3 RS10)

N 26°44'15"W
298.88'

N 9°08'30"E
343.06'

SKETCH FOR CORNER RECORD
CARLILE PROPERTY PER 1355/114
Por. SE 1/4 Sec. 16. T12N-R7E M.D.M.
Unincorporated Territory of Placer County
Ralph Miller, LS 3639 July 2007

N 80°51'30"W
25.00'

N 9°08'30"E
80.00'

Found 3/4 bar LS 2515 3 RS 10

Record Tie to SE Cor.
Sec. 16 (S52°28'E 2201.53')
(3 RS 10)