


CORNER RECORD

Document Number 20100039

City of _____ County of _____, California

Brief Legal Description LOTS 14 & 15, TAHOE VISTA SUBDIVISION NO. 1, B/MAPS/10 O.R.P.C.



Sec. 13
T. 16N.
R. 17E.
M.D. B & M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
USED RECORD DIMENSIONS AND FOUND MONUMENTS PER B/MAPS/10 O.R.P.C. TO RE-ESTABLISH THE MISSING CORNERS OF LOTS 14 & 15, AS SHOWN ON ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:
Ø SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429
• FOUND MONUMENT AS SHOWN ON PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 01, 2010
 Signed Matthew S. Webb P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined and filed December 1, 2010
 Signed Leslie Amshery P.L.S. or R.C.E. No. 6584
 Title Deputy





County Surveyor's Comment _____

BOOK 14 CORNER RECORDS, PAGE 10

PLAT OF SURVEY

LOTS 14 & 15, TAHOE VISTA SUBDIVISION NO. 1, AS FILED IN BOOK B OF MAPS AT PAGE 10, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF THE N.W. 1/4 OF SECTION 13, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 9/1/2010



- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- DIMENSION PT (NOTHING FOUND OR SET)

J/N 1858.00

BOOK 14 CORNER RECORDS PAGE 10