


CORNER RECORD

Document Number 20100038

City of _____

County of PLACER, California

Brief Legal Description LOT 491, DOLLAR POINT No. 7 SUBDIVISION, I/MAPS/41 O.R.P.C.



Sec. 33
T.16 N.
R.17 E.
M.D.B.#M

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 9/3/2010

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSION AND FOUND MONUMENTS PER I/MAPS/41
O.R.P.C. TO RE-ESTABLISH THE MISSING CORNERS OF LOT 491,
AS SHOWN ON ACCOMPANYING PLAT.


A description of the physical condition of the monument as found and as set or reset:

1 SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429
• FOUND MONUMENT AS SHOWN ON PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on September 07, 2010

Signed [Signature] (P.L.S or R.C.E. No. 7429)



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed DECEMBER 1, 2010

Signed [Signature] (P.L.S or R.C.E. No. 6584)

Title Deputy





County Surveyor's Comment _____

BOOK 14 CORNER RECORDS PAGE 13

PLAT OF SURVEY

LOT 491, DOLLAR POINT SUBDIVISION NO. 7, AS FILED IN BOOK 1 OF MAPS AT PAGE 41, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 33, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 9/3/2010



BOOK 14 CORNER RECORDS PAGE 13

- (1) BK. I MAPS, PG. 41
 - FOUND MONUMENT AS SHOWN HEREON
 - SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- NOTE: 1/2" IRON PINS ARE FOUND THROUGH OUT DOLLAR POINT SUBDIVISION, AND ARE ACCEPTED AS ORIGINAL

J/N 1884.00