


CORNER RECORD

Document Number 20130081

City of _____

County of PLACER, California

Brief Legal Description PARCEL 1, 30 P.M. 89, SEC. 3, T. 12 N., R. 7 E., M.D.M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAV88
 Meas. Units: Metric Imperial

Date of Survey OCTOBER 30, 2013

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

MONUMENTS WERE FOUND DURING SURVEY PRIOR TO CONSTRUCTION. AFTER CONSTRUCTION, MONUMENT WAS RESET IN ITS ORIGINAL LOCATION.

A description of the physical condition of the monument as found and as set or reset: _____


MONUMENTS WERE FOUND AS SHOWN ON 30 P.M. 89.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Nov. 19, 2013.

Signed Michael Costa P.L.S. or R.G.E. Number 6600



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received _____ and examined

and filed January 29 2014.

Signed Leslie Amshery P.L.S. or R.G.E. Number 6584


Title County Surveyor


County Surveyor's Comment _____





BORPEL CORNER RECORDS, PAGE 10

LEGEND

DIMENSION POINT 
NOTHING FOUND OR SET

FOUND 1" IRON PIPE W/PLUG 
"LS 5854" PER 30 P.M. 89

FOUND 1" IRON PIPE W/PLUG "LS 5854" DESTROYED DURING CONSTRUCTION. REPLACE WITH 1/2" REBAR WITH PLASTIC CAP "LS 6600" IN ASPHALT. 



PARCEL 2
30 P.M. 89

PARCEL 1
30 P.M. 89

