


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of Rocklin

Document Number 20140009

Brief Legal Description City monuments found in Block I, Book A Maps, Page 28



S. 19
T. 11 N
R. 7 E

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 7/28/97

COORDINATES

(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner --- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

Found standard City of Rocklin monument well with copperweld monument stamped as shown on sketch and also described on 27 PM 20, in Block I, Book A Maps, Page 28.

A description of the physical condition of the monument as found and as set or reset:

Well monuments were tied out prior to removal during the Pacific Street Reconstruction project. After completion of construction, new monuments were set in the same position of the removed monuments.
Set 1-3/8" diameter brass disc in concrete cross walk stamped "LS 6376".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction
 in conformance with the Professional Land Surveyors' Act
 on March 3 20 14
 Signed Richard A. Marino
 L.S. or R.C.E. Number 6376 Expiration Date 12/31/14



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 ____
 and examined and filed March 7, 2014 20 ____
 Signed Leslie Amberry Title County Surveyor
 L.S. or R.C.E. Number 6584 Expiration Date _____



County Surveyor's Comment _____

BOOK 16 CORNER RECORDS PAGE 86

LEGEND:

☉ SET 1 3/8" DIA. BRASS CAP LS 6376
IN PLACE OF MONUMENT DESTROYED
DURING PACIFIC STREET CONSTRUCTION.

(1) RECORD INFORMATION PER 27 PM 120

