


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of UNINCORPORATED AREA Document Number 20140098

Brief Legal Description LOT 2 BLOCK "AA" ICE LAKES UNIT #2  
BOOK "G" OF MAPS PAGE 1 O.R.P.C.



SEC. 35  
T. 17 N.  
R. 14 E.  
M.D.M.

CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 10/8/14

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

● = FOUND 1/2" REBAR, NO REFERENCE  
● = FOUND 3/4" IRON PIPE W/ PLASTIC PLUG, L.S 5549 PER BK. 3 CR PG. 62

A description of the physical condition of the monument as found and as set or reset:

○ = SET BATHEY MONUMENT (T-BAR) W/ NAIL & TAG, P.L.S. 8628

JN: 14080

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on NOVEMBER 5 2014.

Signed [Signature] (L.S.) or R.C.E. Number 8628



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 20 \_\_\_\_ and examined

and filed FEBRUARY 5, 2015 20 \_\_\_\_.

Signed [Signature] Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

BOOK 17 CORNER RECORDS PAGE 68

NOTE: THE BEARINGS AND DISTANCES SHOWN ARE RECORD PER "G/MAPS/1 D.R.P.C. NO MATERIAL DISCREPANCIES WITH RECORD INFORMATION WERE FOUND.

