

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20140044

Brief Legal Description Section Corner common to S. 7,8,17 &18 per Bk.31 PM 117

PLS Job No. 833



S. 7,8,17,18

T. 12 N

R. 7 E

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 4/16/14

COORDINATES

(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner --- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Found RR spike in Virginiatown Road; illegible; and shown on 31 PM 117.

A description of the physical condition of the monument as found and as set or reset: _____

Monument was found in good condition, down 0.2', prior to waterline construction. Will have to be revisited after construction to determine status.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyors' Act

on May, 30 20 14

Signed Richard A. Marino

L.S. or R.C.E. Number 6376



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____

and examined and filed September 25 20 14

Signed Leslie Amberry Title County Surveyor

L.S. or R.C.E. Number 6584



County Surveyor's Comment _____

BOOK 17 CORNER RECORDS PAGE 36



FD. RR SPK;
DOWN
0.2'; ILLEGIBLE
© SEC. COR.
31 PM 117

S.7

S.8

NAIL IN WEST
SIDE OF POWER
POLE

26.70'

VIRGINIATOWN RD. (C6068)

24.40'

NAIL IN EAST
SIDE OF FENCE
POST

25.67'

NAIL IN WEST
SIDE OF
SYCAMORE TREE S.18

S.17