


CORNER RECORD

Agency Index Bk. 21 Pg. 58Document Number 20190011City of ROSEVILLE County of PLACER, CaliforniaBrief Legal Description CENTERLINE MONUMENT SIERRA GARDENS DRIVE PER 29-PM-83**CORNER TYPE****COORDINATES (Optional)**

- | | |
|--|---|
| <input type="checkbox"/> Government Corner | <input type="checkbox"/> Control |
| <input type="checkbox"/> Meander | <input type="checkbox"/> Property |
| <input type="checkbox"/> Rancho | <input checked="" type="checkbox"/> Other |

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902

S.6. T.10N. R.07E.

PLS Act Ref.: 8765(d) 8771 8773 Other:Corner/Monument: Left as found Established Rebuilt Pre-Construction Found and tagged Reestablished Referenced Post-Construction


Narrative of corner identified and monument as found, set, reset, replaced, or removed:

 See sheet #2 for description(s):

Found 1-1/2" copperweld in monument well at the centerline intersection of Sierra Gardens Drive with Santa Clara Drive per 29-PM-83. Set lead and brass tag reference points in top of curb to the northwest, in concrete pads to the north and southeast, and set 5/8" rebar with plastic cap, stamped LS7953 in landscaping to southwest, as shown on sheet 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on August 15, 2018Signed [Signature] P.L.S. or R.C.E. No. 7953**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received _____

and examined and filed April 30, 2019Signed [Signature] P.L.S. or R.C.E. No. 6584Title County Surveyor**County Surveyor's Comment**

BOOK 21 OF CORNER RECORDS, PAGE 58

LEGEND

- ✕ SET LEAD & BRASS TAG IN CONCRETE STAMPED PLS 7953 AS A REFERENCE POINT
- ⊗ SET REBAR & PLASTIC CAP STAMPED PLS 7953 AS A REFERENCE POINT
- ⊙ FOUND 1-1/2" COPPERWELD IN MONUMENT WELL PER 29-PM-83
- FOUND 3/4" REBAR AT BC PER 29-PM-83
- ≡ CURB & GUTTER

NOTES

1. THE LOCATION OF FOUND MONUMENTS HAS NOT BEEN SURVEYED IN RELATION TO RECORD MAPS.
2. THE REFERENCE POINTS SHOWN HEREON WERE SET IN ORDER TO PRESERVE THE AS-FOUND LOCATION OF THE MONUMENT PRIOR TO ROAD CONSTRUCTION.



BOOK 21 OF CORNER RECORDS, PAGE 58

