


# CORNER RECORD

Agency Index BK.21 PG 66  
Document Number 20170056

City of ROSEVILLE County of PLACER, California  
Brief Legal Description CENTERLINE MONUMENT WOODCREEK OAKS BLVD PER S-MAPS-27

### CORNER TYPE

### COORDINATES (Optional)



S.20 T.11N. R.06E

- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey July 27, 2017

N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units  Metric  U.S. Survey Foot  
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code §§8801-8819  
 Complies with Public Resources Code §§8890-8902

- PLS Act Ref.:  8765(d)  8771  8773  Other:
- Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found copperweld in monument well at the centerline intersection of Woodcreek Oaks Boulevard with Marblethorpe Drive (westerly) and Jonquil Drive (easterly) per S-MAPS-27 and V-MAPS-43. Set lead and brass tag reference points in top of curb as shown on sheet 2.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyors' Act on August 3, 2017  
 Signed [Signature] P.L.S. or R.C.E. No. 7953



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_  
 and examined and filed April 30, 2019  
 Signed [Signature] P.L.S. or R.C.E. No. 6584  
 Title County Surveyor  
 County Surveyor's Comment \_\_\_\_\_



BOOK 21 OF CORNER RECORDS, PAGE 66

### LEGEND

- ✕ SET LEAD & BRASS TAG IN TOP OF CURB STAMPED PLS 7953
- FOUND COPPERWELD IN MONUMENT WELL PER V-MAPS-43
- == CURB & GUTTER

### NOTES

1. THE LOCATION OF FOUND MONUMENTS HAS NOT BEEN SURVEYED IN RELATION TO RECORD MAPS.
2. THE REFERENCE POINTS SHOWN HEREON WERE SET IN, ORDER TO PRESERVE THE AS-FOUND LOCATION OF THE MONUMENT PRIOR TO ROAD CONSTRUCTION.



BOOK 21 OF CORNER RECORDS, PAGE 66

