


CORNER RECORD

COUNTY OF PLACER T. 13 N. R. 7 E. MOUNT DIABLO MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT APRIL 19 78



T. 13 N., R. 7 E.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
FOUND 2" CAPPED IRON PIPE MON., STAMPED AS SHOWN, AT INTERSECTION OF FENCE LINES PROLONGED. NW & SE BEARING TREES HAVE BEEN DESTROYED BY ROAD CONSTRUCTION. NE & SW BEARING TREES WERE NOT FOUND.

SEE SKETCH BELOW


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

FOUND NO EVIDENCE OF ORIGINAL POST.
FOUND 2" CAPPED IRON PIPE MON. STAMPED →
ACCEPTED THIS MONUMENT AS TRUE CORNER.



CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



NO SCALE
 () DENOTES PER 1855 FIELD NOTES OF E.D. RICHARDSON, DEPUTY SURVEYOR.

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON APRIL 3, 1980
 NO. 2457
 SIGNED: [Signature]
 L.S. or R.C.E. No.: L.S. # 2457



COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED April 8, 1980 AND EXAMINED AND FILED April 24, 1980
 BY: [Signature] L.S. 3798
 TITLE: Deputy County Surveyor
 DOCUMENT No. Book 1, PAGE 60
 STATEMENT ON BACK OF SHEET YES NO

BOOK 1 CORNER RECORDS, PAGE 60