


CORNER RECORD

Document Number _____

City of ROCKLIN

County of PLACER, California

Brief Legal Description LOT 30 STANFORD RANCH PH. II UNIT 1 & 2 (Q-30)
ANGLE POINT SOUTH LINE ±550' EAST OF STANFORD RANCH ROAD



SEC 12
T 11 N
R 6 E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey NOVEMBER 11, 1995

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND NOTHING - REESTABLISHED FROM FOUND ADJACENT
PROPERTY CORNER MONUMENTS PER Q-30

A description of the physical condition of the monument as found and as set or reset: FOUND NOTHING -

SET 5/8" REBAR WITH CAP PLS 4327 - SHELDON

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DECEMBER 8 1995.


Signed Gary K. Sheldon L.S. or R.C.E. Number 4327



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 20 1996 and examined and filed MARCH 26 1996.

Signed John H. Rietsjens Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 5 CORNER RECORDS PAGE 32

STANFORD RANCH ROAD

FOUND 3/4" REBAR
RCE 21478

FOUND 1/2" REBAR
NO TAG

LOT 30
STANFORD RANCH PH. II
UNIT 1 & 2
Q-30

FOUND 1/2" REBAR
NO TAG

PARCEL B
11 PM 103

FOUND NOTHING
SET 5/8" REBAR - FLUSH
W/YELLOW PLASTIC CAP
STAMPED PLS 4327-SHELDON

FOUND 1/2" REBAR
NO TAG

