


CORNER RECORD

Document Number _____

City of _____

County of Placer, California

Brief Legal Description Lot 6 The Residences at Granite Bay Golf Club
The Grove Positions of 14 and 15 T10N R7E MDM Book T of MAPS P636



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found original surrounding monumentation. used Record Data to Reset.

A description of the physical condition of the monument as found and as set or reset: Set 3/4" Rebar with a 2" Aluminum Cap stamped LS 6013


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 3RD 2006
Signed [Signature] P.L.S or ~~R.C.E.~~ No. 6013



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 08-14-07
and examined and filed SEPTEMBER 1 2007
Signed [Signature] P.L.S or R.C.E. No. LS 6158
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 10 CORNER RECORDS PAGE 83

BOOK 10 CORNER RECORDS PAGE 83

OLYMPIC

R=185.00 (REC)
L=49.19
S54°45'08"W
CHD=49.04

N62°22'08"E (REC)
79.67' (REC)

15.00' (REC)

N62°22'08"E (REC)
8.03' (REC)



N18°55'10"W (REC)

GRANITE BAY GOLF CLUB
THE GROVE
BOOK T OF MAPS PAGE 36

LOT 6

LEGEND:

- FOUND BRASS DISK IN MONUMENT WELL STAMPED LS#3475
 - ⊕ FOUND R.R. SPIKE STAMPED LS#3475
 - ⊙ FOUND NAIL & DISK AT 2.0' EXTENSION OR PROPERTY LINE
 - SET 3/4" REBAR WITH ALUMINUM CAP STAMPED LS 6013
- REC GRANITE BAY GOLF CLUB
THE GROVE
BOOK T OF MAPS PAGE 36

138.31' (REC)

N18°55'10"W (REC)
135.72' (REC)

N53°20'27"E (REC)
57.75' (REC)