


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description PARCEL MAP No. 725B1 12-PM-40



SEC. 2
T. 12 N.
R. 6 E.
M.D.M

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey DEC, 03

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND 3/4" IRON PIN IN TRAVELED WAY OF M. COURTNEY Rd. Per PARCEL
MAP No. 725B1 at BOOK 12 of PARCEL MAPS, PAGE 40. O.R.P.C.
ESTABLISHED REFERENCE POINTS FROM FOUND MONUMENT PRIOR
TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:

FROM REFERENCE POINTS SET P-K NAIL WITH 1/4" BRASS WASHER
STAMPED 'PLA CO SURVEY' CENTERED OVER FOUND MONUMENT
AFTER ASPHALT OVERLAY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on FEBRUARY 18 2004.

Signed [Signature] L.S. or R.C.E. Number LS 7887




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February, 19 2004 and examined

and filed MARCH 1 2004.

Signed Charles B. Grant Title DEPUTY COUNTY
LS 6158 SURVEYOR



County Surveyor's Comment _____

BOOK 12 CORNER RECORDS PAGE 40 O.R.P.C. 95

12-PM-40

WISE Rd.

PARCEL A

FOUND 3/4" IRON PIN,
SET P*K NAIL WITH 1-1/4"
BRASS WASHER STAMPED
'PLA CO SURVEY'

Mc COURTNEY Rd.

PARCEL B

MONUMENT SEARCHED FOR,
NOT FOUND

N.T.S.