


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of \_\_\_\_\_ Document Number 20100074

Brief Legal Description 9-ROS-43 RECORD of SURVEY No. 991



<b>S.</b>	<b>CORNER TYPE</b>	<b>COORDINATES</b> (Optional)
<b>T.</b>	Government Corner <input type="checkbox"/>	Control <input type="checkbox"/>
<b>R.</b>	Meander <input type="checkbox"/>	Property <input type="checkbox"/>
	Rancho <input type="checkbox"/>	Other <input checked="" type="checkbox"/>
	Date of Survey <u>Nov. 18, 2010</u>	N. _____
		E. _____
		Zone _____ Datum _____
		Elev. _____

Corner--- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:  
FOUND R\*R SPIKE IN TRAVELED WAY of CAVITI-STALLMAN Rd. PER RECORD of SURVEY  
No. 991, BOOK 9 of SURVEYS, PAGE 43 D.R.P.C. FROM FOUND MONUMENT  
ESTABLISHED REFERENCE POINTS PRIOR TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:  
FROM REFERENCE POINTS SET MAG-NAIL w/ 1/4" BRASS TAG STAMPED  
" PLACER CO SURVEYOR" CENTERED OVER FOUND MONUMENT.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on DECEMBER 14 2010.  
Signed [Signature]  
L.S. or P.C.E. Number 7887 Expiration Date Mar. 31, 2011



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received \_\_\_\_\_ 20\_\_\_\_\_  
and examined and filed MARCH 4 2011.  
Signed [Signature] Title Deputy County Surveyor  
L.S. or P.C.E. Number 6584 Expiration Date 12-31-2011



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

BOOK 14 CORNER RECORDS PAGE 39



MONUMENT SEARCHED FOR, NOT FOUND.

Fd. R&R SPIKE, NO LEGIBLE MARKINGS, SET MAG-NAIL W/ 1-1/4" BRASS TAG STAMPED "PLACER CO SURVEYOR"

E.P. (byp.)

9-ROS-43

**NOTE:**  
 THIS CORNER RECORD REPRESENTS THE AS FOUND LOCATION OF THE MONUMENTS SHOWN HEREON. NO SURVEY HAS BEEN MADE OF SAID MONUMENTS. THE RELATIONSHIP OF FOUND MONUMENTS TO 9-ROS-43 HAS NOT BEEN DETERMINED BY THIS CORNER RECORD.