

# CORNER RECORD


Document Number 2012 0026

City of \_\_\_\_\_

County of PLACER, California

Brief Legal Description SEC COR 17 | 8 | 9 | 16 PER BM AA MAPS 41

T10N R6E



### CORNER TYPE

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey JAN 2006

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner  Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
A 2" BRASS DISC PER BOOK AA OF MAPS, PAGE 41, DESTROYED DURING CONSTRUCTION

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
2" BRASS DISC, MARKED FOR SECTION CORNER (SEE PAGE 2)

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on JANUARY 4, 2006

Signed Tom D. Morrow

L.S. or R.C.E. Number L.S. 5161




### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 4, 2012 and examined and filed April 23, 2012.


Signed Leslie Amsberry title Deputy County Surveyor

County Surveyor's Comment: \_\_\_\_\_




BOOK 15 CORNER RECORDS PAGE 01

FOUND 1" IRON PIN IN MONUMENT WELL  
STAMPED "RCE 2333" 4.43' NORTH & 2.95'  
EAST FROM SECTION CORNER PER BOOK AA  
OF MAPS. PAGE 41



SET 2" BRASS DISC WITH PUNCH MARK IN  
MONUMENT WELL. REPLACED 2" BRASS  
DISC WITH PUNCH MARK PER BOOK AA OF  
MAPS. PAGE 41



FOUND 5/8" REBAR WITH CAP  
STAMPED "LS 6376" PER 17  
R.O.S. 121

BOOK 5 CORNER RECORDS PAGE 57

