

CORNER RECORD

Document Number


20130086

City of _____

County of

PLACER

California

Brief Legal Description LOT 43, DOLLAR POINT UNIT NO. 1 SUBDIVISION, F/MAPS/73 O.R.P.C.

SEC. 33
T. 16 N.
R. 17 E.
M.D.B. & M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 10/11/2013

COORDINATES (OPTIONAL)

N. _____
 E. _____
Zone _____ Datum _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

CORNER- Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSIONS PER F/MAPS/73 O.R.P.C., FOUND MONUMENTS PER 3/CR/30 & 3/CR/32 O.R.P.C. AND FOUND MONUMNET OF NO RECORD TO REESTABLISH THE MISSING CORNER OF LOT 43, AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429

FOUND MONUMENT AS SHOWN ON PLAT

DIMENSION POINT (NOTHING FOUND OR SET)

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the

Land Surveyors Act on October 10, 2013

Signed [Signature] P.L.S. or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed November 22, 2013

Signed [Signature] P.L.S. or R.C.E. No. 6584

Title Deputy County Surveyor





COUNTY SURVEYOR'S COMMENT:

PLAT OF SURVEY

LOT 43, DOLLAR POINT UNIT NO. 1 SUBDIVISION, AS FILED BOOK F OF MAPS AT PAGE 73, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 33, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 60' DATE OF SURVEY 10/11/2013



BOOK 16 CONVEYER RECORDS PAGE 61

- FOUND MONUMENT AS NOTED
- DIMENSION POINT (NOTHING FOUND OR SET)
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429 (UNLESS OTHERWISE NOTED)
- (1) PER 3/CR/30
- (2) PER 3/CR/32

J/N 2224.00