


CORNER RECORD

Document Number _____

City of AUBURN

County of PLACER, California

Brief Legal Description Plat NW 1/4 Sec 11 T12N R26E M.D.M. Parcel "A" 28-PM-143



CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey _____

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FIND. EXIST. CORNERS AS SHOWN. CALC'D POSITION OF MISSING CORNERS
AS NOTED RESET IN RECORD POSITION

A description of the physical condition of the monument as found and as set or reset:

RESET MISSING MONUMENTS W/ 3/4" REBAR W/ PLASTIC CAP STAMPED RCB 29265

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 12/11-04

X Signed R.G. Hillman P.L.S or R.C.E. No. RCB 29265



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received FEB 28, 2005

and examined and filed MARCH 7 2005

Signed Charles B. Grant P.L.S or R.C.E. No. LS 6158
LICENSE EXPIRES 3-31-06

Title _____

County Surveyor's Comment _____



BOOK 9 CORNER RECORDS PAGE 56

- FND 3/4" IRON PIN TAGGED RCE 11171
- FND 3/4" IRON PIN TAGGED LS 4154
- RESET MISSING CNR W/ 3/4" REBAR W/ PLASTIC CAP STAMPED RCE 29265

