

CORNER RECORD

Document Number _____

City of UNINCORPORATED

County of PLACER, California

Brief Legal Description LOT 8 H-MAPS-61 Pt 1 Sec 8 T13N R8E M.D.M.



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey 1-31-05

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial


Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FND 3/4" REBAR W/ ALUMINUM CAP RLB 9093 @ NE 1/4 SW CORN. USED THESE LOCATIONS TO COMPUTE POSITION OF 2 MISSING CORNERS AND RESET IN RECORD LOCATION

A description of the physical condition of the monument as found and as set or reset: SET @ MISSING CORNERS 3/4" REBAR W/ PLASTIC CAP STAMPED RLB 29265


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 1-31-05
Signed R.G. Hillman P.L.S. or R.C.E. No. 29265



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 7 2005
and examined and filed APRIL 26 2005
Signed Charles B. Grant P.L.S. or R.C.E. No. LS 6158
Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 9 CORNER RECORDS PAGE

60

- FND. 3/4" REBAR W/ALUM. CAP RCE 9093
- SET 3/4" REBAR W/PLASTIC CAP RCE 29265
- NOTHING FND. NOTHING SET



UNITED STATES OF AMERICA

LOT 8
TODD VALLEY ESTATES
UNIT No 1
H-MAPS - 61

PARCEL A' 20 PM 109

LOT 7
N02°22'36"E
3309

N50°31'E 35597'

LOT 9
N03°48'40"E 22474'

R=770 ch=N83°34'47"E 6931'
45-09-35

N81°00'E 11500'

R=1030 ch=N83°12'20"E 7928'

TODD VALLEY RD. J 2123

BOOK 4 CORNER RECORDS PAGE 60