


CORNER RECORD

Document Number

20140073

City of _____

County of PLACER, CaliforniaBrief Legal Description LOT 379, DOLLAR POINT UNIT 6 SUBDIVISION, I/MAPS/15 O.R.P.C.

SEC. 33
T. 16 N.
R. 17 E.
M.D.B. & M.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 07/14/2014

COORDINATES (OPTIONAL)

N. _____
 E. _____
Zone _____ Datum _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

CORNER- Left as Found Found and Tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

USED RECORD DIMENSIONS AND FOUND MONUMENTS PER I/MAPS/15, 8/CR/84, AND UNRECORDED MONUMENTS FOUND IN RECORD POSITION TO REESTABLISH THE MISSING CORNERS OF LOT 379, AS SHOWN ON THE ACCOMPANYING PLAT.

A description of the physical condition of the monument as found and as set or reset:

- SET 5/8" REBAR WITH YELLOW PLASTIC CAP LS-7429 (UNLESS OTHERWISE NOTED)
 FOUND MONUMENT AS SHOWN ON PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the

Land Surveyors Act on July 30, 2014

Signed [Signature] (P.L.S.) or R.C.E. No. 7429



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed DECEMBER 17, 2014

Signed [Signature] P.L.S. or R.C.E. No. 6584

Title County Surveyor




COUNTY SURVEYOR'S COMMENT:


PLAT OF SURVEY

LOT 379, DOLLAR POINT UNIT 6 SUBDIVISION, AS FILED PER BOOK 1 OF MAPS AT PAGE 15, OFFICIAL RECORDS PLACER COUNTY, CALIFORNIA. A PORTION OF SECTION 33, TOWNSHIP 16 N., RANGE 17 E., M.D.B. & M.

SCALE 1" = 50' DATE OF SURVEY 07/14/2014



BOOK 17 CORNER RECORDS PAGE 54



- FOUND MONUMENT AS SHOWN HEREON
- SET 5/8" REBAR WITH YELLOW PLASTIC CAP L.S. 7429
- (1) PER 1/MAPS/15 (NOTE: 1/2" IRON PINS ACCEPTED AS RECORD)
- (2) PER 8/CR/84

J/N 2368.00