

CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____

Brief Legal Description PARCEL MAP No. 70013 1-PM-110

	NE 1/4 SEC. 3 T. 12 N. R. 8 E. M.D.M.	CORNER TYPE		COORDINATES (Optional)	
	Government Corner <input type="checkbox"/> Meander <input type="checkbox"/> Rancho <input type="checkbox"/> Date of Survey <u>MAY 10, 05</u>	Control <input type="checkbox"/> Property <input checked="" type="checkbox"/> Other <input type="checkbox"/>	N. _____ E. _____ Zone _____ Datum _____ Elev. _____		

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND R-R SPIKE 6" BELOW A.C. SURFACE IN TRAVELED WAY OF
LUTHER RD. PER PARCEL MAP No. 70013 AT BOOK 1 of PARCEL MAPS,
PAGE 110, O.R.P.C. FROM FOUND MONUMENT ESTABLISHED REFERENCE
POINTS PRIOR TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:


FROM REFERENCE POINTS SET P-K NAIL W/ 1/4" BRASS WASHER STAMPED
"PLA CO SURVEY" CENTERED OVER FOUND MONUMENT AFTER ASPHALT
OVERLAY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on DECEMBER 15 20 05.

Signed [Signature] L.S. or R.C.E. Number L.S. 7887




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DEC. 22 20 05 and examined

and filed JAN. 5 20 06.

Signed Charles B. Grant L.S. 6158 Title DEPUTY COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 10 CORNER RECORDS PAGE 34

LUTHER Rd.

27-PM-91

CACHE Ct.



FOUND R&R SPIKE 6" BELOW A.C.
 SURFACE, SET P*K NAIL W/1-1/4"
 BRASS WASHER STAMPED "PLA
 CO SURVEY"

FOUND 2" C.I.P.
 WITNESS CORNER

1-PM-110

