


CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

City of _____ Document Number _____
Brief Legal Description Lot 41, Chamberlands Addition Unit No. 2 Book H MAPS 6



T.14N. R.16E

CORNER TYPE

COORDINATES (Optional)

Government Corner Control N. _____
Meander Property E. _____
Rancho Other Zone _____ Datum _____
Date of Survey _____ Elev. _____

Corner— Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

• ~ fd. 1/2" bar as per H MAPS 6

A description of the physical condition of the monument as found and as set or reset:

∅ ~ set 5/8" bar LS 5886

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyor's Act on December 20 01

Signed [Signature] L.S. or R.C.E. Number 5886
Thomas C. Buswell


COUNTY SURVEYOR'S STATEMENT

This Corner Record was Received Dec. 31, 20 01 and Examined

and filed MARCH 21, 20 02

Signed [Signature] Title COUNTY SURVEYOR

County Surveyor's Comment _____



BOOK 7 CORNER RECORDS PAGE 58

