

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of _____

Document Number _____

Brief Legal Description PARCEL MAP No. 73178

14-PM-63



Sec 2
T.12 N.
R.6 E.
M.O.M.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey DEC, 03

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

FOUND 3/4" CAPPED PIPE IN TRAVELED WAY OF Mc COURTNEY ROAD Per PARCEL MAP No. 73178, Book 14 of PARCEL MAPS, PAGE 63 O.R.P.C. ESTABLISHED REFERENCE POINTS FROM FOUND MONUMENT PRIOR TO ASPHALT OVERLAY.

A description of the physical condition of the monument as found and as set or reset:


FROM REFERENCE POINTS SET P.K NAIL w/ 1/4" BRASS WASHER STAMPED "PLA CO SURVEY" CENTERED OVER FOUND MONUMENT AFTER ASPHALT OVERLAY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land

Surveyors' Act on December 29 2003.

Signed [Signature] L.S. or R.C.E. Number LS 7087




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received January, 14 2004 and examined

and filed MARCH 1 2004.

Signed [Signature] Title DEPUTY COUNTY SURVEYOR
LS 6158



County Surveyor's Comment _____

14-PM-63

PARCEL "A"

PARCEL "B"

Mc COURTNEY RD.

FOUND 3/4" CAPPED PIPE-UNREADABLE
SET P*~~K~~ NAIL W/ 1-1/4" BRASS WASHER
STAMPED "PLA CO SURVEY"

