CORNER RECORD

COUNTY OF PLACER T. 16 N R. 17 E MDM. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☒

CORNER IDENTIFICATION – DATE OF VISIT JUNE 14 19 87

60' R.P. TO THE NORTHWEST CORNER OF
LOT 92 - RIDGEWOOD HIGHLANDS NO. 2
"F" MAPS 52

CORNER – LEFT AS FOUND ☐ FOUND AND TAGGED ☒ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 5/8" REBAR FOR R.P. TO THE NORTHWEST CORNER OF LOT 92.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

PLACED 3/4" CAPPED IRON PIPE, STAMPED LS 4415 - 1987, OVER TOP OF REBAR. CONSTRUCTED SMALL ROCK MOUND AROUND MONUMENT AND NAILED U.S.F.S. "LAND SURVEY MONUMENT" SIGN ON TREE TO ~~WEST~~ EAST OF MONUMENT.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



Book 1, Corner Records, Page 152

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON OCTOBER 27 19 87

SIGNED: [signature]

L.S. or R.C.E. No. LS 4415

LICENSED LAND SURVEYOR RONALD S. DUNDAS No. 4415 CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED Oct. 30 19 87

AND EXAMINED AND FILED Nov. 4 19 87

BY: Bari L. McDaniel

TITLE: DEPUTY COUNTY SURVEYOR

DOCUMENT No. _____