CORNER RECORD

COUNTY OF PLACER, CALIFORNIA

Brief Legal Description Lot 14, Northstar Unit 2, J/Maps/54 CORNER TYPE T17N Government Corner Control Meander Property Meander Date of Survey 10-12-10 Corner - Left as found Found and tagged Established	COORDINATES (Optional) N E ZoneNAD27 NAD83 NAD83 Epoch Elev Vert. Datum: NGVD29 NAVD88 Meas. Units: Metric Imperial
T17N Government Corner	N ENAD27
Corner - Left as found Found and tagged Established [Reestablished 🗵 Rebuilt 🗌
Identification and type of corner found: Evidence used to identify or procedure See sketch on back.	e used to establish or reestablish the corner:
Found 1/2" rebar in record position at the Northerly corner of Lot 15. Found	nd 1/2" rebar in record position at the
Westerly corner of Lot 14. Found 3/4" iron pipe in record position at the Ea	asterly corner of Lot 14. Found 3/4" and
5/8" rebars in record positions along the Easterly line of Martis Landing.	
A description of the physical condition of the monument as found and as s See sketch on back. Set 5/8" rebar tagged LS 6819 in record location.	
SURVEYOR'S STATEMENT	MAL LAND
This Corner Record was prepared by me or under my direction in conform the Land Surveyor's Act on	MASUDA DE LS 6819 SE EXPIRES: 4
This Corner Record was received	- CED LAND SUP
and examined and filed, JANUARY 31, 2011 Signed Aud B. Junt P.L.S or B.C.E. No. 6158	CHARLES B. GRANT
Title, COUNTY SURVEYOR	Exp. 3-31-12 No. 6158
County Surveyor's Comment	OF CALIFORNIE

