


# CORNER RECORD

Agency Index 20180115 Bk 21 Pg 43  
 Document Number \_\_\_\_\_

City of UNINCORPORATED AREA County of PLACER, California

Brief Legal Description LOT 7 PAINTED ROCKS ESTATES  
BOOK "V" OF MAPS AT PAGE 2 P.C.D.R.



**CORNER TYPE**  
 SEC.28 Government Corner  Control   
 T.16N. Meander  Property   
 R.16E. Rancho  Other   
 M.D.M. Date of Survey 9/28/18

**COORDINATES (Optional)**  
 N. \_\_\_\_\_ E. \_\_\_\_\_  
 Elevation \_\_\_\_\_  
 Units  Metric  U.S. Survey Foot  
 Horizontal Datum \_\_\_\_\_  
 Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_  
 Vertical Datum \_\_\_\_\_  
 Complies with Public Resources Code 8801-8891  
 Complies with Public Resources Code 8890-8902

PLS Act Ref:  8765(d)  8771  8773  Other:

Corner/Monument:  Left as found  Established  Rebuilt  Pre-Construction  
 Found and tagged  Reestablished  Referenced  Post-Construction

Narrative of corner identified and monuments as found, set, reset, replaced, or moved:

See sheet #2 for description(s):

- = FOUND COPPER WELD MONUMENT L.S. 4751 IN MON. WELL PER "V"/MAPS/2 P.C.D.R.
- = FOUND 3/4" REBAR W/ COPPER COLLAR L.S. 4751 PER "V"/MAPS/2 P.C.D.R.
- = FOUND 3/4" REBAR PER "V"/MAPS/2 P.C.D.R., TAG MISSING

○ = SET BATHEY MONUMENT (T-BAR) W/ NAIL & TAG STAMPED P.L.S. 8628

JN:18143

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
 the Professional Land Surveyor's Act on OCTOBER 23, 2018

Signed [Signature] P.L.S. or R.S.E. No. 8628  
LIC. EXP. 12/31/19



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_  
 and examined and filed DECEMBER 23, 2018

Signed [Signature] P.L.S. or R.S.E. No. 6584  
 Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

Book 21 CORNER RECORDS, PAGE 43

