


CORNER RECORD

COUNTY OF Placer T. 16N R. 11E MDB& MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT Nov. 2, 19 77



Southwest corner Section 10

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found a Rock mound and bearing trees

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED



PACIFIC GAS AND ELECTRIC CO.
LAND DEPT. JOB LD 4099

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

*Ed. rotted stump
& remains of oak*

Ed Rock mound



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON No. 377 August 2 19 78

SIGNED: _____

[Signature]
LS 3797

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED August 8, 19 78 AND EXAMINED AND FILED November 21, 19 78

BY: Med. [Signature] LS 3798
TITLE: Deputy County Surveyor

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO

Book 1, Corner Records, Page 50