California E. X U.S. Survey Foot Other: Pre-Construction Post-Construction CORNER RECOR PS LS5753

CORNER RECORD

BK 22, PG 79 Agency Index Document Number 20090071 City of County of **PLACER** Brief Legal Description PARCEL 3 OF 24 PM 151, ORPC. SEC. 9, T.14, R.9 E. M.D.M **CORNER TYPE COORDINATES (Optional)** Sec. 9, T. 14 N. R. 9E. Government Corner Control Elevation Meander Property Units Metric Rancho Other Horizontal Datum Zone **Epoch Date** Date of Survey August 4, 2009 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Left as found Corner/ Established Rebuilt Monument: Found and tagged Reestablished Referenced Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): USED FOUND ORIGINAL MONUMENTS AND RECORD DIMENSIONS PER 24 PM 151 TO RE-ESTABLISH N'LY CORNER OF PARCEL 3 AS SHOWN ON PAGE 2. SET 3/8 REBAR TAGGED "L.S. 5753" AS SHOWN ON PAGE 2. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on August 10, 2009 Signed P.L.S. or R.C.E. No. **COUNTY SURVEYOR'S STATEMENT** This Corner Record was received and examined and filed Signed Title County Surveyor's Comment

LEGEND

- FOUND 3/4" REBAR W/ALUM.CAP L.S.4598 PER 24 PM 151
- O SET 3/8" REBAR WITH TAG L.S.5753 PER THIS SURVEY

NOTE ALL BEARING AND DISTANCES ARE RECORD AND MEASURED

