


(For County Use Only)

CORNER RECORD

COUNTY OF Placer T. 12N R. 8 E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT 4/17/86 1986



CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Corners lost, established from adjacent corners on Parcel Map 7/PM/109

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
Set 3/4 inch rebars with copper sleeve marked LS 3062, per attached map.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

See attached map.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 4/25 1986

SIGNED: Emerson L. Smith

L.S. or R.C.E. No.: LS 3062



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED MAY 12 1986
AND EXAMINED AND FILED MAY 15 1986

BY: Debra Richards
TITLE: DEPUTY COUNTY SURVEYOR


DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES

NO

Book 1, Corner Records, Page 138



- = FND. 5/8" REBAR PER 7/PM/109 (1)
- = FND. 3/4" PIPE PER 7/PM/109 (1)
- = SET 3/4" REBAR WITH COPPER SLEEVE MARKED LS3062

CORNER REMONUMENTATION MAP
 PARCEL "D" OF 7/PM/109, PORTION SEC. 3, T12N R8E.
 SURVEYED FOR DAVID JOHNSON
 SCALE: 1" = 50'
 EMERSON L. SMITH
 LS 3062
 APRIL 1986