


CORNER RECORD

COUNTY OF Placer T. 11N R. 8E MDM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER Property Corner

CORNER IDENTIFICATION - DATE OF VISIT May 31 19 89




CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Found 5/8" Rebar LS4898 at NE, SE and SW corners of Lot 13 and 3/4" Rebar at the Radius
point of North Lakeshore Blvd., per N Maps 46.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED Set 3/4" Rebar at NW and SW corners
of Lot 13 Swiegart Estates Unit #2

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



1"=100'
 →
 • FO. 3/4" RE-BAR
 • FO. 5/8" RE-BAR LS 4898
 • SET 3/4" RE-BAR LS 5109

890050


SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON May 31 19 89

SIGNED: Gerald D. Distingher No. 5109

L.S. or R.C.E. No.: LS5109

SEAL



COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED 6/14 19 89 AND EXAMINED AND FILED 6/23 19 89

BY: John Rutgers TITLE: DEPUTY COUNTY SURVEYOR

DOCUMENT No. _____ STATEMENT ON BACK OF SHEET

YES NO

BOOK 1, CORNER RECORDS, PAGE 188