


CORNER RECORD

Document Number 20150098

City of Roseville

County of Placer, California

Brief Legal Description LOT 1, P MAPS 56 AND 21 PM 112 O.R.



SEC. 33, T.11 N., R.6 E.

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 10/13/2015

COORDINATES(Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NADV88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
USED RECORD DIMENSIONS AND FOUND MONUMENTS PER BOOK P OF MAPS AT PAGE 56 AND
BOOK 21 OF PARCEL MAPS AT PAGE 112, TO REESTABLISH THE MISSING CORNERS OF LOT 1,
AS SHOWN ON THE ACCOMPANYING PLAT

A description of the physical condition of the monument as found and as set or reset: _____
SEE ATTACHED PLAT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on MARCH 8, 2016.

Signed [Signature] P.L.S. or R.C.E. No.: PLS 9010



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ and examined

and filed June 30, 2016.

Signed [Signature] P.L.S. or R.C.E. No.: 6584

Title County Surveyor

County Surveyor's Comment _____



