

CORNER RECORD


COUNTY OF PLACER, CALIFORNIA

City of Unincorporated

Document Number 20160039

Brief Legal Description SOUTH LINE PARCEL A; 18PM149 AND 29PM63; CHILI HILL ROAD

PLS Job No. 833



S. 11

T. 12 N

R. 7 E

CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 8/11/16

COORDINATES

(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____


Corner --- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:
Property corners tied out per CR Book 17, Page 59 were destroyed due to pipe line construction.

A description of the physical condition of the monument as found and as set or reset:
Re-set new RR spikes per CR Book 17, Page 59.


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction
 in conformance with the Professional Land Surveyors' Act
 on September 13, 20 16
 Signed Richard A Marino
 L.S. Number 6376



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 20 _____
 and examined and filed October 19 20 16
 Signed Leslie Amberry Title County Surveyor
 L.S. or R.C.E. Number 6584



County Surveyor's Comment _____

BOOK 19 CORNER RECORDS PAGE 15

NOTE: DATA WITHIN ()
SIGNIFIES RECORD
INFORMATION PER 29 PM 63.
NOT FIELD VERIFIED

