


CORNER RECORD

Document Number _____

City of _____

County of PLACER, California

Brief Legal Description LOT 23 CEDAR FLAT SUBDIVISION, FOUND IN BOOK H, MAPS PAGE 82. P.C.R.



T16N
R.17E

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8-23-95

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE SKETCH BACK


A description of the physical condition of the monument as found and as set or reset:

SEE SKETCH BACK

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on AUGUST 30, 1995.

Signed [Signature] L.S. or R.C.E. Number 3422



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEB 5, 1997 and examined

and filed FEBRUARY 7, 1997.


Signed [Signature] Title COUNTY SURVEYOR



County Surveyor's Comment _____

BOOK 5 CORNER RECORDS PAGE 75

BOOK 5 CORNER RECORDS PAGE 75



(R) = RECORD PER BOOK H OF MAPS AT PAGE 82.

PLAT OF SURVEY

LOT No. 23, CEDAR FLAT SUB. RECORDED IN BOOK H OF MAPS,
 AT PAGE No. 82, ALSO BEING A PORTION OF THE NE 1/4 OF
 SECTION 28, TOWNSHIP 17 NORTH, RANGE 17 EAST, M.D.B. & M.
 COUNTY OF PLACER CALIFORNIA
 NOT OT SCALE AUGUST 23 1995