


**CORNER RECORD**

COUNTY OF PLACER T. 14N R. 16E M.D.B. MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION - DATE OF VISIT OCT. 10, 1990



LOT 272 CHAMBERLANDS UNIT 'G' 'I' MAPS 6

CORNER - LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH \_\_\_\_\_

• ~ FOUND 1/2" φ REBAR w/ COPPER SLEEVE, STAMPED L.S. 2515, UNLESS OTHERWISE NOTED.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED \_\_\_\_\_

Q ~ SET 5/8" φ REBAR w/ YELLOW PLASTIC CAP STAMPED L.S. 5886

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD  N/A  
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_



CHUKAR CIRCLE (50' R.O.W.)



(R) ~ RECORD  
 (M) ~ MEASURED

R = 25.00'  
 Δ = 90°00'00"  
 L = 39.27'  
 CH = N45°00'00"W 35.36'(R)  
 CH = N45°02'57"W 35.34'(M)

GROUSE DRIVE (50' R.O.W.)

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON OCT 22, 1990

SIGNED: [Signature]

L.S. or R.C.E. No.: L.S. 5886

SEAL

THIS CORNER RECORD WAS RECEIVED 6/27/91 AND EXAMINED AND FILED 6/28 1991

BY [Signature]  
 TITLE: DEPUTY COUNTY SURVEYOR

DOCUMENT No. \_\_\_\_\_  
 STATEMENT ON BACK OF SHEET

YES  NO

BOOK 4, CORNER RECORDS, PAGE 54